

NEW!
NOUVEAU!**+5K**
NEW PICS!
NOUVELLES PHOTOS !**CONTROL ARMS / BRAS DE SUSPENSION**

| CODE | APPLICATION | MOOG | MAS | MEVO | NAPA | POS. | IN STOCK |
|----------|--------------------------------------------------------|----------|---------|-----------|---------|------------------------|-----------|
| CP5412 | 19-15 CHR Jeep Renegade, 19-17 Compass | ☹ | ☹ | CMS251226 | 2608407 | Rr Rr | TBA |
| CP5436 | 19-15 NIS Murano | ☹ | ☹ | CMS301220 | 2608566 | w/Ball Joint Fr RH Lwr | TBA |
| CP5437 | 19-15 NIS Murano | ☹ | ☹ | CMS301221 | 2608567 | w/Ball Joint Fr LH Lwr | TBA |
| CP5445 | 14-11 FOR Edge, 15-11 Lincoln MKX | ☹ | CA85646 | CMS401144 | 2608281 | Rr Up | TBA |
| CP5462 | 10-05 FOR Mustang | ☹ | CA86575 | CMS401246 | 2608539 | Rr Up | TBA |
| CP5542 | 19-16 HON CR-V, Civic, 19-18 Accord | ☹ | ☹ | CMS601237 | 2608471 | Rr Lwr Fr | TBA |
| CP5553 | 18-15 VOLK Golf/GTI/Golf Sportwagen | ☹ | CA43283 | CMS701140 | 2608446 | Fr LH Lwr | In Stock |
| CP5554 | 18-15 VOLK Golf/GTI/Golf Sportwagen | ☹ | CA43284 | CMS701141 | 2608447 | Fr RH Lwr | In Stock |
| CP5557 | 18-13 MAZ CX-5 | ☹ | ☹ | CMS761180 | 2608559 | Rr RH Lwr | TBA |
| CP5558 | 18-13 MAZ CX-5 | ☹ | ☹ | CMS761181 | 2608560 | Rr LH Lwr | TBA |
| CP5559 | 16-13 MAZ CX-5 | ☹ | CB65214 | CMS761184 | 2608432 | w/Ball Joint Fr RH Lwr | TBA |
| CP5560 | 16-13 MAZ CX-5 | ☹ | CB65213 | CMS761185 | 2608433 | w/Ball Joint Fr LH Lwr | TBA |
| CP5563 | 18-14 MAZ 3 | ☹ | ☹ | CMS761209 | 2608599 | Rr Up | In Stock |
| CP5569 | 18-14 MAZ 3 | ☹ | CB65203 | CMS761215 | 2608540 | w/Ball Joint Fr LH Lwr | TBA |
| CP5570 | 18-14 MAZ 3 | ☹ | CB65204 | CMS761216 | 2608541 | w/Ball Joint Fr RH Lwr | TBA |
| CP5575 | 18-09 SUB Forester, 18-10 Legacy, Outback | ☹ | LA72615 | CMS801048 | 2607792 | w/Ball Joint Rr Lwr Fr | TBA |
| CP5591 | 18-06 LEX IS350, 2018 IS300, 17-16 IS200t, 15-06 IS250 | ☹ | CB64117 | CMS861136 | 2607909 | w/Ball Joint Fr LH Up | TBA |
| CP5592 | 18-06 LEX IS350, 2018 IS300, 17-16 IS200t, 15-06 IS250 | ☹ | CB64118 | CMS861137 | 2607910 | w/Ball Joint Fr RH Up | TBA |
| CP5638 | 19-17 KIA Sportage, 19-16 Optima, Hyundai Tucson | ☹ | CB63253 | CMS901233 | 2608520 | w/Ball Joint Fr LH Lwr | In Stock |
| CP5639 | 19-17 KIA Sportage, 19-16 Optima, Hyundai Tucson, | ☹ | CB63254 | CMS901234 | 2608521 | w/Ball Joint Fr RH Lwr | In Stock |
| CP5640 | 18-13 HYU Santa Fe, Santa Fe XL (AWD) | ☹ | ☹ | CMS901235 | 2608575 | Rr Up | TBA |
| CP5644 | 19-14 KIA Soul, 19-15 Soul EV | ☹ | ☹ | CMS901241 | ☹ | w/Ball Joint Fr LH Lwr | TBA |
| CP5645 | 19-14 KIA Soul, 19-15 Soul EV | ☹ | ☹ | CMS901242 | ☹ | w/Ball Joint Fr RH Lwr | TBA |
| CP5646 | 18-15 KIA Sorento | ☹ | ☹ | CMS901247 | 2608647 | w/Ball Joint Fr LH Lwr | In Stock |
| CP5647 | 18-15 KIA Sorento | ☹ | ☹ | CMS901248 | 2608648 | w/Ball Joint Fr RH Lwr | In Stock |
| CP5654 | 15-13 HON Civic, Acura ILX | ☹ | ☹ | ☹ | 2607577 | w/Ball Joint Fr RH Lwr | TBA |
| CP5655 | 15-13 HON Civic, Acura ILX | ☹ | ☹ | ☹ | 2607578 | w/Ball Joint Fr LH Lwr | TBA |
| TK200187 | 17-07 CHR Jeep Wrangler, 2018 Wrangler JK | K200187 | ☹ | MS25435 | 2671490 | Bushing Fr Up | In Stock |
| TK200268 | 11-04 GM Chevrolet Malibu, 10-05 Pontiac G6 | K200268 | BK90630 | MS50477 | 2749370 | Bushing Fr Lwr Rr | TBA |
| TK200781 | 12-07 TOY Camry, 10-04 Sienna, 07-01 Highlander, | K200781 | BC74369 | MS861119 | 2673819 | Bushing Fr Lwr Fr | In Stock |
| TK400018 | 19-11 GM Chevrolet/GMC Silverado/Sierra 2500/3500 | K400018 | IA90289 | MS50914 | 2683725 | Idler Arm w/Bracket Fr | Feb. 2021 |
| TK620053 | 10-01 GM Chevrolet/GMC Silverado/Sierra 1500 HD | CK620053 | CB91250 | CMS501230 | ☹ | w/Ball Joint Fr Up | TBA |
| TK622906 | 18-12 FOR Focus, 19-16 Escape, 18-14 Transit Connect | RK622906 | CB85334 | CMS401150 | 2608157 | w/Ball Joint Fr RH Lwr | TBA |
| TK622907 | 18-12 FOR Focus, 19-16 Escape, 18-14 Transit Connect | RK622907 | CB85333 | CMS401151 | 2608158 | w/Ball Joint Fr LH Lwr | TBA |
| TK622964 | 17-15 CHR 200, 16-13 Dodge Dart | RK622964 | ☹ | CMS251202 | 2607263 | w/Ball Joint Fr RH Lwr | In Stock |
| TK623000 | 19-13 FOR Fusion, Lincoln MKZ | RK623000 | CB86014 | CMS401184 | 2608615 | w/Ball Joint Fr RH Lwr | Feb. 2021 |
| TK623001 | 19-13 FOR Fusion, Lincoln MKZ | RK623001 | CB86013 | CMS401185 | 2608616 | w/Ball Joint Fr LH Lwr | Feb. 2021 |
| TK642947 | 17-08 HON Accord, 15-12 Crosstour | RK642947 | ☹ | CMS60179 | ☹ | Rr Lwr Rr | TBA |
| TK643095 | 16-07 HON CR-V | RK643095 | CA59606 | CMS601016 | 2607587 | Rr Up | TBA |
| TK643184 | 19-13 FOR Fusion, Lincoln MKZ (FWD All) | RK643184 | ☹ | CMS401198 | 2608327 | Rr Up | TBA |
| TK643284 | 19-16 HON Civic, 19-17 CR-V, 19-18 Accord | RK643284 | ☹ | CMS601238 | ☹ | Adjustable Rr Up | TBA |